



Report No. : INS-000001  
Vehicle / Plate No. : VWX 3212  
Inspector : Stella Cortez  
Inspection Date : 24 Oct 1982

VEHICLE INSPECTION REPORT

Generated 05 Aug 2026, 17:47

SUMMARY

This summary reflects the inspector's on-site assessment recorded during the physical inspection on 24 Oct 1982.

|                  |              |               |              |               |                   |
|------------------|--------------|---------------|--------------|---------------|-------------------|
| ACCIDENT HISTORY | FLOOD DAMAGE | DEFECTS FOUND | ENGINE SOUND | EXHAUST SMOKE | OVERALL CONDITION |
| Minor            | Moderate     | Moderate      | Normal       | Black         | Good - Minor Wear |

VEHICLE & CUSTOMER INFORMATION

|                |                   |                |                           |
|----------------|-------------------|----------------|---------------------------|
| Customer Name  | Autumn Gates      | Customer Email | kykiweqyka@mailinator.com |
| Customer Phone | +1 (388) 319-2335 | Dealership     | Sloane Carroll            |
| Make           | Toyota            | Model          | Vios                      |
| Year           | 2024              | Color          | White                     |
| License Plate  | VWX 3212          | Mileage        | 23456                     |
| Transmission   | CVT               | Inspector      | Stella Cortez             |

INSPECTION CHECKLIST

01. Exterior Inspection

EXCELLENT

Occaecat accusamus s



02. Interior Inspection

GOOD

Cupidatat ut distinc

03. Underhood Inspection

FAIR

Reprehenderit dolore

04. Cut & Joint Inspection

POOR

Nulla velit doloribu

05. Accident History Check

MINOR

Nisi voluptatum ut e

06. Flood Damage Check

MODERATE

Nisi quia et et id s

07. Engine Sound

NORMAL

Totam non consequatu

08. Exhaust Smoke

BLACK

Error ut consequatur

09. Defect

MODERATE

Tempora voluptates d

10. Test Drive

GOOD

Voluptatem Nostrud

11. Overall Assessment

EXCELLENT

In vero quia ut ulla

ADDITIONAL NOTES

No comment